


"DOTTEREL".
Special Survey.

Condition of vessel under repair at time of
handing over.

Special Survey completed. New Load Line
Certificates to be applied for and issued
near sailing date.

Report written.



002808-002815-0012

Keelsons _____

"

efficient ? _____

4/10

Transoms, Pointers & Crutches _____

Timbers of Frame _____