

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME Dunda Rpt. Jan No. 54156
8850
885-1
885-2

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Cladding Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Cladding Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32).

Type of Engine T. 3 Cy. 20 1/2", 35" & 59" — 42"
361 N.H.P.

If Boilers fitted with forced draught No
Tail Shaft. If fitted with a continuous liner No
If fitted with an outside gland of } Yes
approved type

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed + LMC 2.34

3 SB 220 lbs.

L.C.
28/2/34. [Signature]

