

Rpt. C 12(a).

FREEBOARD VERIFICATION FORM FOR ORDINARY CARGO ^{AND}_{OR} PASSENGER SHIPS.

When received in London Office JAN 9 1939
 Port Sunderland
 Name "JOSEWYN" (EX WHITWOOD)
Official No. 143104No. in Reg. Book 86368Port of Registry (~~For Foreign Ships~~) "SWANSEA"Iron or Steel Steel State whether Classed by Lloyd's Register + 100 A1Name of Owners JOSEWYN S.S. Co Ltd Date of Verification 7th Jan 1939

I have to report that the Freeboards as given below, assigned by the Committee to this ship, have been correctly marked on the ship's sides, in accordance with the printed instructions:

FREEBOARD AMIDSHIPS FROM ^{upper} TOP OF DECK LINE, WOOD /STEEL DECK.		FROM CENTRE OF DISC.	
Tropical Fresh Water	1 ft. 3 ins.	8 ins.	above
Fresh Water	1 ft. 6 ins.	5 ins.	above
Tropical	1 ft. 8 ins.	3 ins.	above
Summer	1 ft. 11 ins.		
Winter	2 ft. 2 ins.	3 ins.	below
Winter North Atlantic	2 ft. 5 ins.	6 ins.	below

Maximum Summer Draught corresponding to the freeboard assigned as shown on the Builders' Displacement Scales:—

*certificates returned
in collection*

[Signature]

Surveyor.

(To be filled up in London Office.)

Statement No. 27499 Date of Committee's Minute14-5-32

Particulars for Record in Register Book.	Moulded Depth	19 ft. 9 ins.	x
	Freeboard	1 ft. 11 ins.	x
	Corresponding Draught	18 ft. 0 ins.	x

Freeboards compared and found correct by [Signature] Date 9/1/39Is fee paid? L.L.2-25/3/41 Form for Certificate

Instructions Date

Certificate written 2.1.39 Noted for posting