

Chief Surveyors

Received from Chief Surveyors

EL'S NAME *Steel S.S. "GOBEO"*

Report *Jrk*

No. 17786

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 34/5/22.)

re of Survey

When due

Downton pump has been dispensed with (See endorsement dated 21-10-20)

100-A-1. (Steel) "Carrying petroleum in cylindrical tanks"

1 Dk (Steel)

Cell 113 uE 26' f 22' 62t APT 68t

FK 7Bk, pt. Cam, Pleyds Av CP, P38' B96' F23' Mchry aft



#12
11.3.21

is Concluded the bridge deck plating is increased in thickness and a web fitted on frame 4-35 as approved; the number of webframes in the machinery space and the extent of the treble riveted butts of the upper deck finger plate are as approved and not as stated and that the Owners consent has been obtained to the adoption of Steel wire hawsers and warps but Surveyors should be requested to state if this is so

Lt. W. G. H.
31/3/21.

See letter
M.H.M.
11.4.21



© 2021

Lloyd's Register Foundation

002830-002837-0020