

Urgent.

2.

FREEBOARD VERIFICATION FORM FOR STEAMERS.

Sunderland When received in London Office

Name "Mozart"

No. _____ No. in Reg. Book _____

Registry (For Foreign Vessels) _____

Steel Steel State whether Classed by Lloyd's Register 100/A Contemplated

of Owners _____ Date of Verification _____

I have to report that the Freeboard from the centre of disc to the top of the deck line, and the lines in connection therewith, as given below, assigned Committee to this vessel, have been correctly marked on the vessel's sides, in accordance with the printed instructions:—

Distance from centre of disc to top of statutory deck line	5	ft.	2	ins.	✓	
Distance from centre of disc to top of statutory deck line at awning or part-awning deck		ft.		ins.		
Fresh water line above centre of disc			6	ins.	✓	
Indian Summer line above centre of disc			4 1/2	ins.	✓	
Winter line below centre of disc			4 1/2	ins.	✓	
Winter North Atlantic line below centre of disc				ins.		
Distance between the top of statutory deck line on vessel's side and the intersection of the continuation of upper side of wood or iron deck with the vessel's side	}	at main, spar or upper dk.		1 3/4	ins.	✓
		at awning or pt.-awning dk.			ins.	

NOTE.—It should be clearly shown whether the statutory deck line is set off from a wood or iron deck.

*Cont. to be sent 10/3/10
for insertion after D.N. is inserted
S. Hill 10/3/10*

Surveyor.

to be filled up in London Office.)

Entry No. _____ Date of Committee's Minute 8.3.10

Freeboard Depth for record ft. _____ ins. _____

Freeboards compared and found correct by _____ date _____

Fee paid? _____ Form for Certificate A

Conditions _____ date _____

Date written 10.3.10 Noted for posting _____



© 2020

Lloyd's Register Foundation