











Twin Screw Steamer "ISLANDER".

Identification Marks on Shafting :-

<u>Crank Shafts:</u>	<u>Starbd.</u>	<u>Port</u>
	LLOYDS 1533 R.W.F. 28-3-29	LLOYDS 1542 R.W.F. 28-3-29
<u>Thrust Shafts.</u>		
	LLOYDS 8471 553 J.P. 3-7-29  13-8-29	LLOYDS 8471 552 J.P. 3-7-29  13-8-29
<u>Screw Shafts.</u>	<u>Starbd. Working</u>	<u>Port Working.</u>
	LLOYDS 286 J.H. 31-5-29	LLOYDS T.284 J.H. 3-5-29
	<u>Starbd. Spare</u>	<u>Port Spare</u>
	LLOYDS T.283 J.H. 3-5-29	LLOYDS 285 J.H. 31-5-29

Intermediate Shafts:

<u>Starbd.</u>	LLOYDS	LLOYDS	<u>Port.</u>	LLOYDS	LLOYDS
	394 J.P.  15-8-29	8380 422 J.P. 4-4-29  13-8-29		8378 415 J.P. 28-3-29  26-7-29	8378 417 J.P. 28-3-29  26-7-29
	LLOYDS 8378 406 J.P. 28-3-29  26-7-29	LLOYDS 8374 405 J.P. 26-3-29  13-8-29		LLOYDS 8378 416 J.P. 28-3-29  13-8-29	LLOYDS 8380 423 J.P. 4-4-29  15-8-29

Arthur B. Palmer
Surveyor to Lloyd's Register of Shipping
18-9-29



© 2020

Lloyd's Register
Foundation

002876-002882-0193