

S/R

F.E.

Im, 9.37.

Received by Chief Ship Surveyor .....

Received from Chief Ship Surveyor .....

VESSEL'S NAME Stl. Single Sc.M. Tanker "CORYDA" Rpt. Rot. No. 27299a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

(\*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No.	<u>15640</u>	Depth "d"	<u>-</u>
2nd Long. No.	<u>42780</u>	Proportions = $\frac{L}{D}$	<u>13.52</u>
Framing	<u>As approved</u>	Sheerstrake	<u>As approved</u>

This is a sister ship to the "CLEA"

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed  100A1 "Carrying petroleum in bulk"

1 Dk., 2nd Dk. clear of cargo tanks, "Longitudinal framing at bottom and at deck"

Cell. DBuE 64' 156t, DTf 25' 262t, FPT 135t, APT 83t.

FK, 17BH., LLOYD'S A & CP.  
P 91', B 43', F 48'  
Machy. aft

O.L. 483.3'.

Not Noted



*[Handwritten signatures]*  
22.9.38

To Be broken up



© 2021

Lloyd's Register Foundation

002907-002915-0088