

LLOYD'S REGISTER OF SHIPPING



Propeller and outside fastenings.
 All painting arrangements (tested)
 Electrical Survey complete.
 All boilers (forward port, centre and starboard)
 examined internally and externally together with safety
 and mounting and safety valves adjusted under steam.
 Main engine and auxiliaries generally examined and
 working conditions.

Port of Piraeus,

14th August, 1959.

This is to Certify that I have

under working conditions

Surveyed the Boiler^s and machinery of the S.S. "COLUMBIA" 8473 tons gross of Panama, whilst lying afloat & in the Govt. Graving Dock at Piraeus, on the 9th August, 1959 and subsequently on account of General Examination for voyage to Japan as an Unclassed vessel. Also on account of Main Boiler and Docking Surveys,

and that I have transmitted to the Committee of Lloyd's Register of Shipping, London, a Report, as on the other side, stating that all repairs recommended by me have been completed to my satisfaction.

P.T.O.

E. J. Rad.


Engineer Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Parts now examined for General Examination for Unclassed Vessel.

- Propeller and outside fastenings.
- All pumping arrangements (tested)
- Electrical Survey complete.
- All boilers (forward port, centre and stbd., aft port, centre and stbd.) examined internally and externally together with safety valves and mountings and safety valves adjusted under steam.
- Main engine and auxiliaries generally examined and tried under working conditions.



14th August, 1929.

This is to Certify that I have

under working conditions
 Surveyed the Boiler and machinery of the S.S. "COLUMBIA" 873 tons
 Gross of Panama, whilst lying afloat & in the Govt. Graving Dock
 at Pinaros, on the 9th August, 1929 and subsequently on account of
 General Examination for voyage to Japan as an unclassified vessel.
 Also on account of Main Boiler and Docking Surveys,


and that I have transmitted to the Committee of Lloyd's Register
 of Shipping, London, a Report, as on the other side, stating
 that all repairs recommended by me have been completed to

my satisfaction.

P.T.O.

Engineer Surveyor to Lloyd's Register

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
 "While the Committee of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021
 Lloyd's Register
 Foundation