

F.E.

by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Stl Se Hopper Barge "RUKAMAVATI"* Rpt. *RLH* No. *16872*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

P. Long
Transverse No. *1778* Depth "d" *11.50*

Framing: Table No. *✓* Description *angle frames as approved*

Longitudinal No. *5893*

Proportions Length *10.94*
Depth =

Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✠ 100A.1. (Steel) "Hopper Barge" for Service in the Gulf of Kutch
IDK (Stl)
M.Ts 20t.
F.K, 4 B, pt Cem, pt Asp, Lloyds A + CR

[Signature]

23.2.26.

It is concluded the notation "pt Cem" should be recorded in the Register Book but the surveyor should be requested to ^{write} restate if this is so.



001938-001946-0207