

20 OCT 1958

Received from Chief Ship Surveyor

NAME "COLONEL CROMPTON" REPORT Gms. No. 27628.  
AR.

Standing Conditions of Class: None.

Assessment of Certificate (~~As before~~ or None)

Place of Present Survey: (Afloat and in dry dock)

Docking; W & T repairs; damage (cause unknown) involving shell plates C.9 & 10 (p.s. from fwd.).

Recommendation: SUBMITTED record of 'DS 9,58' be assigned as recommended.

DS 9,58.

INSERT IN S.R.L. APPENDIX.

Shell plates C.9<sup>v</sup> & 10 (p.s. from fwd.) indented.

*78*  
*10-10-58*  
© 2021



Lloyd's Register  
Foundation

003029-003037-0001