

# LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

Holbergsgade 11, Copenhagen, K.

Telegrams: Engineers Copenhagen

Telephones: Centr. 5760 & Bu. 3192

RECEIVED

- 7 AUG 1952

5th August, 1952.

And 29/8

The Secretary,  
Lloyd's Register of Shipping,  
London.

Dear Sir,

M.s. "Gard".

This vessel, a transversely framed tanker, has been under survey at this port. A considerable number of the tanks have been examined internally and the shell, deck and bulkheads drilled as required by the circular letter dated 28th May, 1952.

We would draw your attention to the drillings given in our Rept. 8 forwarded to-day. The deterioration of the bottom and side shell and decks is small and no additional strengthening has been fitted at this time.

The inner surface of the bottom and side shell, deck and bulkheads is in good condition. The pitting on the internal surface of the bottom shell is of a minor nature.

Yours faithfully,

*S. Clausen*

SURVEYOR TO LLOYD'S  
REGISTER OF SHIPPING



© 2021

Lloyd's Register  
Foundation

003065-003074-0073



CLASSIFICATION

Holbergsgade 11, Copenhagen, K.

WALDOYD'S REGISTER OF SHIPPING

© 2021  
Lloyd's Register  
Foundation

W. S. "Gard".

MS

20-8-52. Tu

[illegible]