

Form 7a

For the information of Surveyors and the Committee only.

Received at \_\_\_\_\_ Office, \_\_\_\_\_ 19\_\_

# Lloyd's Register of Shipping.

**BARRY.**

(Report on Machinery, No. \_\_\_\_\_ Port \_\_\_\_\_)

No. **123**

## ENGINE or BOILER VALVES or CONNECTIONS.


I have to report that the Details, as herein described, ~~manufactured~~ **repaired**  
 by **C.H. Bailey, Ltd.** of **Barry**  
 for the ~~Engines~~ **Centre** Boilers ~~in~~ of ~~being constructed by~~ **s.s. "PAN"**  
 \_\_\_\_\_ ~~is~~

have been inspected by me as set forth below, and found to be, so far as can  
 be seen, sound and free from defects.

**This has fitted**  
~~There have been~~ ~~repaired~~ to **vessel at Barry**

Stamp Mark.

**LLOYD'S TEST**  
 \_\_\_\_\_ **500** lbs.  
 No. **123**  
**19.8.48. JEA.**



Number and Description.	One G.M. steel for centre boiler blow down valve.
Hydraulic Test: lbs. per square inch.	500lbs/□".
Other Tests, if any.	-
Dates when Inspected.	19. 8. 48.