

Rpt. 8

REPORT OF SHIP SURVEYS AND REPAIRS

Received London

24 MAY 1963

Ship's Name ~~SEMS~~ " BRITISH PEER" Gross tons 8861  
 Is there a rpt. 9? No Port GLASGOW Rpt. No. 94495  
 No. of visits Two First date 3-5-63 Last date 7-5-63  
 Interim Cert. issued No. rpt. Damage rpt. issued Not  
 & copy herewith 10 attached & copy herewith? reqd. Last rpt. (H.Q. only) - 1753 SUZ  
 Date of completing rpt. 7-5-63 Surveyed at, if different from Port above GRANGEMOUTH  
 Surveyed afloat and/or in D.D. Afloat Last date of examination in D.D.  
 Has a Load Line Yes, part see  
 Survey been held? body of report. Freeboard Marks verified No.

State which additional Rpt. 8 is attached: (Cont); (PS); (DR); (EQ); (Rig) - (PS) Tanker

Survey fees £15. 15. -d. Damage fee - Expenses £1. -s. -d.

entry made in RFB.

8/5/63.

Surveyor's Initials.

*Amula*

S.A. fee

I have surveyed the above ship in accordance with the Rules for **CONDITION SURVEY**  
 At the request of the owners, a condition survey was carried out, as far as practicable, while the ship was lying afloat at GRANGEMOUTH, on 3rd May, 1963 and subsequently, for the purpose of issuing a Report 10, to permit the ship to proceed to a Spanish Port, under tow, and in ballast condition.

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.  
**Now done:** An examination was made of weather decks, superstructure, bulkheads with their closing appliances, casings, companionways, coamings, hatchways and their closing appliances, ventilators and deck openings. Windlass and equipment, found or placed in satisfactory condition.

Anchors made ready for easy working. Rudder and tiller firmly fixed in centreline position, side scuttles and deadlights efficiently closed. All doors, locks, etc., found or placed in good condition.

Prior to departure the towing superintendent indicated that he was satisfied with the condition of the ship, for the contemplated voyage.

REPORT 10 ISSUED TO TOWING SUPERINTENDENT, COPY ATTACHED.

I recommend that this ship remain as classed with/without fresh record of dry docking

FOR THE INFORMATION OF THE COMMITTEE.

(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate.)

Date of Committee GLASGOW 21 MAY 1963

Mimute

Transmit to London.

*Alister M. Cameron*  
 Surveyor to Lloyd's Register of Shipping

(ALISTER M. CAMERON)

ALSO FOR
SPL FOR
TRO
SRL
POSTING
HEADER
CERT

Lloyd's Register Foundation

008116-003123-0013 1/2

Rpt. 8 (P.S.) TANKER

Ship's Name ~~SS~~/MS "BRITISH PEER"

S.S. ( ) Due

Port GLASGOW

Rpt. No. 94495.

Examined & condition		Examined & condition		
In dry dock from	} Afloat	* Hatchways	Good	
" " " to		* Ventilators	Good	
Shell plating	Not examined	* Air & sounding pipes	Above deck - good	
Sternframe	↓ Good	Doublers under sounding pipes	Not examined	
Rudder		Steering arrangements (main)	} See Body of report	
Was rudder lifted?		" " (aux)		
Plating, etc. in way of shell openings		Windlass		
Side scuttles & deadlights		Good	Masts & rigging	Not examined
Overbd. scuppers & discharges		Not examined	Hand pumps & suction	"
Hold		↓ Good	W.T. doors	Good
F.P. spaces			Bulwarks, freeing ports, etc.	Good
Chain locker			Summer freeboard as verified	Not verified
A.P. spaces			<u>EQUIPMENT:</u>	
Engine space	Equipment letter		d +	
Boiler space	Anchors: No. on board		3B	
Under E. & B.	Cables {		State if ranged	/ Stateed to complete Dia.
Coal bunker			Length on board	
Tunnel & well			Mean dias. range from	
Cement, asphalt, etc., on btm. shell	Rule length			
Weather decks	Good	Mooring ropes		
* Casings	Good	Other items:		
* Deckhouses	Good			
Superstructures	Good			
* Skylights	Good			
Companionways	Good			

EXAMINED & CONDITION		TANKS	TESTED & CONDITION	
PORT	STARBOARD		PORT	STARBOARD
/		F.P. Tank		
		A.P. Tank		
		Deep Tank No. 1		
		" " No. 2		

For other tanks see overleaf

These items to include their closing appliances

where a part Special Survey and, say, dry docking Survey are held at the same time, the items for SS should be marked "For SS".

© 2020  
 Lloyd's Register  
 Alister M. Cameron  
 Surveyor to Lloyd's Register of Shipping  
 (ALISTER M. CAMERON)

0013 2/2

EXAMINED & CONDITION

TESTED & CONDITION

EXAMINED & CONDITION				TANKS	TESTED & CONDITION				
Port	Port Ctre.	Stbd. Ctre.	Starboard		Port	Port Ctre.	Stbd. Ctre.	Starboard	
				No. 1 Cargo tank					
				.. 2 .. ..					
				.. 3 .. ..					
				.. 4 .. ..					
				.. 5 .. ..					
				.. 6 .. ..					
				.. 7 .. ..					
				.. 8 .. ..					
				.. 9 .. ..					
				.. 10 .. ..					
				.. 11 .. ..					
				.. 12 .. ..					
				Pump room forward					
				.. .. amidships					
				<b>NOT .. <sup>E</sup>aft EXAMINED</b>					
				Cofferdams					
				Structure around cargo suction pipe strums					
				O.F. bunkers					
				Settling tanks					
				D.B. tanks					
				D.B. cofferdams					
				Other items					



© 2020

Lloyd's Register Foundation



rtific  
While  
d, it  
er to  
the  
mitt