


Lloyd's Register of Shipping.

REPORT ON ANNUAL LOAD LINE SURVEY.


Name of Ship "BLOOMFIELD PARK" Official Number 175583 Port of Registry Montreal
Place of Survey Trinidad, B.W.I. Dates of Survey 27th February 1946 Date of last Load Line Survey 2nd Oct. 1944

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs. Necessary.	Date effected.	
HATCHWAYS, INCLUDING SMALL HATCHWAYS.				
1. Exposed on freeboard deck.				
Coamings, their stays and stiffeners	/			
Beams				
Fore and afters				
*Covers				
*Tarpaulins				
(State number per hatchway)				
*Cleats and battens				
Lashings and their fittings				
Wedges				
(Is supply, including spares, adequate ?)				
2. Exposed on superstructure decks, including raised quarter decks.				
Coamings, their stays and stiffeners				
Beams				
Fore and afters				
*Covers				
*Tarpaulins				
(State number per hatchway)				
*Cleats and battens				
Lashings and their fittings				
Wedges				
(Is supply, including spares, adequate ?)				
3. Within superstructures not intact or not protected by Class I closing appliances.				
Coamings	Good			
Beams	Good			
Fore and afters				
Covers	Good			
Tarpaulins	Good			
(State number per hatchway)	(one per hatch)			
Cleats and Battens	Good			
Wedges	Good			
(Is supply, including spares, adequate ?)	Yes			
VENTILATORS IN EXPOSED POSITIONS.				
4. To spaces below freeboard deck.				
Coamings, their supports and deck connections	/			
Closing arrangements				
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.				
Coamings, their supports and deck connections				
Closing arrangements				
AIR PIPES.				
6. Exposed on freeboard and superstructure decks.				
Closing arrangements				
7. Within partially enclosed superstructures.				
Closing arrangements				
MACHINERY CASINGS.				
8. Casing Top.				
Fiddley openings, their covers and fastenings	/			
Skylights, their fastenings, covers and lashings				
9. Exposed on freeboard and raised quarter decks.				
Doors and fastenings				
10. Exposed on superstructure decks other than raised quarter decks.				
Doors and fastenings				
11. Within partially enclosed superstructures.				
Doors and fastenings	Good			
12. FLUSH BUNKER SCUTTLES and chain attachments				
...				
13. COMPANIONWAYS, including deckhouses enclosing ladderways.				
Doors, fastenings, covers				

© 2020
Lloyd's Register

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effect
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	Good Good		
Bridge, fore end			
Bridge, after end			
Poop			
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures			
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves			
17. SIDE SCUTTLES AND DEADLIGHTS			
18. GUARD RAILS			
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways			
20. LIFELINES (fittings and material)			
21. FREEING PORTS.			
Shutters			
Protection bars			
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances			
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
24. LOAD LINE MARKS			

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
3, 11, 14.	<i>J. C. Cutbitt</i>	Trinidad, B.W.I.	27th February 1946

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *J. C. Cutbitt* Place *Trinidad B.W.I.* Date *27th February 1946*

Signature *J. C. Cutbitt*

Date *27th February 1946*

Fee *\$12.00*

Number of Visits *One*

Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11 should be reported on Form C 11 (contd.) and attached to the Form C 11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.