


NAME OF VESSEL . ."BANDON".

Extract from freeboard verification of marking form
received from the Bangkok . Surveyors dated 13.2.52 .

Shoulded depth	10	ft.	4	ins.
Corresponding draught	8	ft.	9 $\frac{1}{4}$	ins.
Shoulded depth as shown on draught sheet.	10	ft.	4	ins.
Tropical freeboard	1	ft.	5	ins.
Summer	"	1	ft.	7 $\frac{1}{4}$ ins.
Winter	"	not	ft.	assigned ins.
W.N.A.	"	not	ft.	assigned ins.
Fresh Water Allowance			2	ins.

Marked from ~~wood~~/steel upper deck.

Checked by 
Dated . . 19.5.52