

1m, 10, 11

1 E

Received by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

VESSEL'S NAME

Ocean Viscount

REPORT

*Richmond No. 23
L.A. 46
47
48*

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

"The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Triple Expansion.

If Boilers fitted with forced draught

Yes

Tail Shaft. If fitted with a continuous liner

Yes


If fitted with an outside gland of approved type

No

The main engines have been constructed under the supervision of the American Bureau of Shipping.

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *LMC(R) 6.42.*

*L.H.
6/19/42.*



LONDON
 bt fitted
 r minute
 3
 lled to axis
 und eye-hole
 YES
 r made water
 CONTINU
 rosive TIC
 after end
 opeller 5
 face 117
 is at work
 is at work
 attached
 ge Pumps a
 k (Size
 Bilge
 ve Engine K
 RS IN B
 bilges
 deep water
 overing pla
 ETS & S
 very spaces
 n ENTRAN
 OILERS
 e inch
 y Boilers
 DAL FIR

ter Capacity
 Tons.
 124
 166

are the principal additional spare gear supplied