

1

Sent to Chief Surveyor's _____

Received from Chief Surveyors _____

VESSEL'S NAME Steel S.S. "MATHURA". Report Gls. No. 40685**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey _____

When due _____

✱ 100 A.1.


2 Dks. (Steel) 3¹/₂ Dk. (Steel) in No. 1 hold.

Cell DB 454', 2117t. MT 35', 1490t. DTa 40', 1568t.

EPT 111t. APT 90t.

FK. 8 BH. pt. Cem. Lloyd's A. & C.P. P49', B223', F42'.

Date of Build 12.20.



© 2020

Lloyd's Register
Foundation

7. 1. 21.

003311-003320-0054