

June 6

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *SUR SR M.V. "KOTA GEDE"* Rpt. *Rot* No. *17819*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

^{1st Long} Transverse No. *15019* Depth "d" *13.7*

Framing: Table No. *-* Description *Built angle frames as approved.*

^{2nd} Longitudinal No. *42143*

Proportions Length *13.4*
Depth =

~~Deck~~ Sheerstrake *as approved.*

Revised Rules

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

100 A-1 (Steel) Carrying vegetable oil in deep tanks
3 DECK (SIL - Upper DE Teak S)
bell DE. 378' 1472 t, D.T. f 28' 950 t, DTA 37' 767 t, FPT 562, APT 46 t.
FK, 8 BH (1BH to 2nd DE + 1BH to 3rd DE), pt cem, Lloyds A+CP.
P 51', B 150', F 61'.

[Signature] *S.P.R. 13-10-28*



© 2020 Lloyd's Register Foundation