

Received by Chief Engineer Surveyor _____

Received from Chief Engineer Surveyor _____

VESSEL'S NAME

Henning Maersk

Rpt.

*Cpm
Ham*

No.

9869

21836

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(*The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine

Oil Engines 4. S.C.S.A.

7cy. 29 1/8" - 59 1/16"

If Boilers fitted with forced draught

no main boiler

Tail Shaft. If fitted with a continuous liner

yes

If fitted with an outside gland of approved type

no

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed *+ Linc. 3. 36*

2.0B. 180 lb.

*Ham
21. 3. 36*



© 2021

Lloyd's Register
Foundation

003341-003348-0131