

1m, 8.21.

*Sunnyhell*  
*ese*

*PAKURA*  
*PAKURA*

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME *Steel S. S. "Maja"* Rpt. *Rot.* No. *12558*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. *42.5* Depth "d" *12.5*

Framing: Table No. *3* Description *Bull Angles*

Longitudinal No. *7650*

Proportions Length = *10.*  
Depth =

*Upper* Deck Sheerstrake *as approved*



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

*100 A1 (Steel)*

*1 DK (Steel) Well Deck.*

*bell DB. a 35' u 6.14' f 81 171 t. FPT 246, APT 156.*

*FK. 4BH. Cem. ATCP. Q 52' B 51', F 22'*



Lloyd's Register Foundation

003391-003400-0268

Angles on upper edge	22"	22"	Angle on ditto	3 x 3 x
Spacing			Tie Plates	<i>practically plates</i>