

Are the cylinders fitted with safety valves

yes

Are the exhaust pipes and ~~water~~ water cooled or ~~clogged with~~ clogged with

Engine  
Boiler

No. 14971/2

Made by

Bohn & Kahler

For


"STANVAC NAIROBI" (EX JAMES J. MAGUIRE)

Kel

Report No.

837

It is submitted that a copy of this Report be  
forwarded to the Intended Surveyors for their  
~~returned~~ guidance and for completion.



Jm

© 2020

Date

24/3/53.

Lloyd's Register  
Foundation

5m.1.53.

003458-003465-0359

Are the cylinders fitted with safety valves

Are the lubricating arrangements of