

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "ROSA" Rpt. Ams No. 13379a

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 4958 Depth "d" -
2nd Long. No. 23718 Proportions = L/D 22.7
Framing bulb angle frames as approved Sheerstrake as approved



This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

- 100A1 Carrying petroleum in bulk
1 Dk Longitudinal framing at bottom in Centre Tanks and at trunk top
FPT 123t APT 105t
FK, 10 HH, pt. cem. pt. asp., Lloyd's A & CP
Q 87' Trunk 209' F 39'
Machy. aft

Handwritten signatures and date 5.3.35



© 2020 Lloyd's Register Foundation

003487-003494-0173