

1

Leonidas + Leonidas *

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME SLS BELLORADO Report brk No. 48385
18954

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/53.

Nature of Survey 1st Entry

When due Should Rule



✠ 100 A.I. (Steel)

2 D^{cs} (Stl)

Cell D.B 33i 1012t, D.T.a 30' 784t, A.P.T. 16t

F.K, "Intermediate" between D^{cs} B.H in after hold dispensed with
"H B.H to upper D^{cs}, 2 B.H to 2nd D^{cs}" pt Cem, Rlays A/CP

P 33', B 112', F 44'.



© 2020

Lloyd's Register Foundation

003513-003524-0288