

LJUBJANA X

F.E.

"Dunar."

Received by Chief Ship Surveyor 18/0/2

Received from Chief Ship Surveyor

VESSEL'S NAME

At St Karpat

Rpt.

Mc

No. 63/38

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/32.)

Transverse No. 79.92

Depth "d" 23.66


Framing: Table No. 3 Page 16

Description as approved

Longitudinal No. 30209

Proportions Length = 10.98
Depth =

Bridge Deck Sheerstrake and strake below in one
plate of approved thickness to give equivalent
strength.



This vessel appears to have been built in accordance with the
Rules and the approved plans, and it is submitted she is eligible to
be classed + 100A-1. (Stat.) as recommended.

+ 100A-1. (Stat.)

1 Dr (pt. Lin. - pt. Oct)

WB. Keel D Ba 132 u 22 1/2 + 157 99pt D Ta 26 908 FPT 1514

APT/DBL

FK. 7BH Cam. Lloyds A V 60 P 35 8230 FH2



Lloyd's Register
Foundation

003513-003524-0328