

12 JAN 1961

16 JAN 1961

Date of writing report 9/1/61
Survey held at HULL

Received London
No. of visits 1

Port HULL
First date and Last date 2/1/61
No. 66488

REPORT OF PERIODICAL SURVEYS & REPAIRS OF MACHINERY

No. in R.B. 52125 Name S.S. Trawler "ARCTIC TRAPPER"
Owners Boyd Line Ltd. Managers T.W. Boyd Gross tons 465 Date of build 1937 1
Engines made Hull By Charles D. Holmes & Co., Ltd. Port of Registry Hull
No. of Main Engines 1 No. of Screws 1 Type Triple Expansion
No. of Main Boilers 1 W.P. 215 lb.
No. of Aux./Donkey Boilers - W.P. -
Surveyed Afloat or in Dry Dock On slipway
Nature of Survey D.S.
Was Damage Report issued? No Int. Cert.? Yes
Last Report (For Head Office only)

Records of Survey & Special Notations as per Register Book

Hull	Machinery
100A1 trawler 3,60	LMC 7,57
s.s. 7,57	MBS 4,60
	TSCL 6,59
	sps 7,57

The condition of any of the following items is to be described as "good" only when the part has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where it is considered that re-examination or repairs should be effected before the due date of the next Periodical Examination a distinguishing mark thus † should be inserted against the item and the circumstances and action recommended described fully under "defects and repairs". At part or complete Special Surveys those items which are not applicable to the ship should be cancelled with a black line; this need not be done when the machinery is on a continuous survey basis. When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

DOCKING Propellers Good Wear Down of Stern Bushes 1/16" Oil Glands Sea Connections Good
Fastenings Good Has Screwshaft Tubeshaft been drawn? No Date of Examination - Has Shaft been changed? -
Has Shaft now fitted been previously used? - Has Shaft now examined/fitted a continuous liner? - Approved oil gland? -

MAIN ENGINES (Recip. Steam or I.C.) PORT STARBOARD

1 Cyls., Covers, Pistons & Rods
2 Valves & Gears
3 Connecting Rods, Top Ends & Guides Side Centre
4 Crankpins & Bearings Side Centre
5 Journals & Bearings

MAIN ENGINE DRIVEN AIR COMPRESSORS

6 Cyls., Covers, Pistons & Rods
7 Connecting Rods & Top Ends
8 Crankpins & Bearings
9 Journals & Bearings
10 Coolers & Safety Devices

MAIN ENGINE DRIVEN SCAVENGE PUMPS

11 Cyls., Covers, Pistons & Rods
12 Connecting Rods & Top Ends
13 Crankpins & Bearings
14 Journals & Bearings
15 Levers
16 SCAVENGE BLOWERS

17 SUPERCHARGERS

MAIN TURBINES

18 Casings, Rotors, Blading, Bearings & Thrusts

19 EXHAUST STEAM TURBINES (WITH RECIP. ENGINES)

20 STEAM COMPRESSORS

21 CLUTCHES & HYDRAULIC COUPLINGS

22 REDUCTION GEARING

23 THRUST BLOCKS, SHAFTS & BEARINGS

24 INTERMEDIATE SHAFTS & BEARINGS

25 HOLDING DOWN BOLTS & CHOCKS

26 CONDENSERS (MAIN & AUX.)

27 STEAM RE-HEATERS

28 DE-SUPERHEATERS

29 STOP & MANOEUVRING VALVES

30 MAIN ENGINE DRIVEN PUMPS

31 CRANKCASE DOORS & EXPLOSION RELIEF DEVICES Have Main Engines been tested working and manoeuvring?

OPINION OF MACHINERY AND RECOMMENDATIONS

The machinery of this vessel, so far as now seen, is in a good condition and is eligible in my opinion to remain as now classed, without fresh record of survey.

Date of Committee TUESDAY 31 JAN 1961
Decision As now

40m,4,57. T. (MADE AND PRINTED IN ENGLAND.)

32 Essential Independent Pumps (Identify by position)
33 Bilge, Ballast & Oil Fuel Suction Lines, Fittings & Controls
34 Have the remaining Piping Arrangements & Fittings in the machinery space been examined as considered necessary?
35 Fresh Water Coolers 36 Lub. Oil Coolers 37 Heaters (state service)
38 Independent Air Compressors, Coolers & Safety Devices
39 Air Receivers & Safety devices—Main 40 Auxiliary
41 Oil Fuel Tanks (Not forming part of hull structure)
42 Evaporators 43 Have Evaporator Safety Valves been tested under steam?
44 Steering Machinery 45 Windlass 46 Fire Extinguishing Arrangements

AUXILIARY ENGINES (Identify by position)
.....
.....

ELECTRICAL EQUIPMENT			
PROPULSION	PORT	STARBOARD	AUXILIARY EQUIPMENT
a Generators			l Generators & Governors
b Exciters			
c Air Coolers			m Motors
d Motors			
e Air Coolers			n Switchboards & Fittings
f Control Gear, Cables, etc.			o Circuit Breakers
g Insulation Resistance			p Cables
h Insulating Oil Test			q Insulation Resistance
i Overspeed Governors			r Steering Gear Generators and Motors
j Magnetic Couplings			s Navigation Light Indicators
k Air Gap			

BOILERS OPENED UP & EXAMINED (Identify by position and state latest date of internal examination of each boiler)
MAIN AUXILIARY, DONKEY or PRESS
.....
Superheaters
Safety Valves
Mountings, Doors & Fastenings
Safety Valves Adjusted to { Sat.
Spt.
Boiler Securing Arrangements
Main Economisers Exhaust Gas Heated Economisers
Steam Heated Steam Generators Steam Generator Safety Valves Adjusted to
Were Oil Burning System & Remote Controls examined working in accordance with Rules? Forced Circulating Pumps
Have Saturated Steam Pipes in cylindrical boiler smoke boxes been examined as required by Rules? Funnel

EXAMINATION & TESTING OF STEAM PIPES (State material)
Main Auxiliary (over 3 in. bore)
Were Copper Pipes annealed? Have Saturated Pipes in cylindrical boiler smoke boxes been tested?

PARTICULARS OF DEFECTS & REPAIRS, ETC. (Damage repairs should be detailed separate from wear and tear repairs; state what action has been taken regarding items which are subjects of class)

Propeller

The tips of all blades of the cast iron propeller were found to be badly corroded. The Owners spare C.I. propeller was fitted with and without key.


LEAVE THIS SPACE BLANK

Survey fees ...

Damage fee ...

Expenses... ..

Date when A/c rendered



© 2020

Lloyd's Register
Foundation

as CLASSIFIED
It is submitted that this
vessel is eligible to remain
with above preference