

Are the Bilge Suction Pipes, Cocks, and Valves arranged so as to prevent any communication between the sea and the bilge

005534-005540-0239


s/s "Rona."

Nwe. Rpt. 70926

It is submitted that  
this vessel is eligible for  
THE RECORD. + LMC 4.18. F.D.

JWR

11/5/18.



© 2021

It is submitted this report be forwarded to the  
Middlesbrough Surveyors for the completion & signature.  
1008w

JWR

Material

Thickness

Pitch of stays

How are stays secured

Working pressure by rules