

Do. of
Do. of
Do. at

1,000,000

1

Sent to Chief Surveyors 25.1.18

Received from Chief Surveyors

VESSEL'S NAME SFE % Mahand Report Enk No. 17238

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey 1st entry When due Pacific Mariner

+ 100 A1 (Steel)
" Carrying fuel oil FP above 150° F in DB & DT. (Col 5)
2 19th (STE) 3rd 19th (STE) in No 1 hold.
Cell 10B 414' 1615t. DTa 37' 1234t. FPT 100t. APT 96t.
FK. 7 BH. Cem. Lloyds ArCP. PH7' B126' FH7'.

M
ME
26.1.18



© 2020

Lloyd's Register Foundation

003556-003556-0003

REAR