

1m.12.15.

F.E.

Received by Chief Ship Surveyor

4.4.17

Received from Chief Ship Surveyor

VESSEL'S NAME

Sheels Strade

Rpt.

Lth

No. 15751

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No.

33.5

Depth "d"

9.25

Framing: Table No.

3 page 9

Description

Bulk angles as approved

Longitudinal No.

4355

Proportions

Length

12.38

Depth

~~Deck~~ Sheerstrake

as approved.

the vessel is without cargo battens

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed ✱ 100 A-1 (Steel) as recommended.

1.0m (pl steel) wall on

F.P.T. 356. A.P.T. 96

F.K. 3BH. Cam. Longitudinal (247. Bg' F 26. "high abt")

The Certificate of Classification, to be endorsed "Cargo battens not fitted," and the same notation to be printed in the Register Book.



© 2021

Lloyd's Register
Foundation

003572-003580-0070

Angles on upper edge

Spacing

Deck, Material and thickness

Hull