

003625-003630-0069

5m. 9.37.

1

Charles Connell & Co. Ltd.

Yard No. 430

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "TRADER" Report Gls No. 63260 & 63260a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey FIRST ENTRY When done

100A1 Subject to permanent repairs to stem and stem plating at Owners' convenience.

2 Dks

Cell DB 362' 1170t, DTa 32' 915t, FPT 50t, APT 63t

FK, 7BH, Cem., Lloyd's A & CP

P 38' B 140' F 46'

O.L. 435.0'

a† The class is assigned and maintained upon the understanding that the equipment will be made to accord with the requirements of the Rules when the present state of emergency has passed.

Insert in S.R.L (45 fathoms of chain cable to be supplied when the present state of emergency has passed)



AKS
8/1/41

© 2020

Lloyd's Register
Foundation