

two liners are fitted, is the shaft lapped or protected between the liners

Is an approved Oil Gland or other appliance fitted


shaft If so, state tune

Engine No. 691110 Made by M. A. L.
Boiler

For Deutsche Werft - A.G. No. 187.

Bran Report No. 1799.

It is submitted that ~~a copy of~~ this Report be
forwarded ~~to the~~ Surveyors for their
returned ~~guidance and for completion.~~ retained in this
office pending completion, a copy having
been forwarded to the Hamburg Surveyors.



1m, 6, 36.

they each fitted with a Discharge Valve always accessible on the plating of the vessel

Are the Blow Off Cocks fitted with a spigot and br

How are they protected