

F.E.

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME *Plt. Se. K. "LORD LORD"* Rpt. *Hull* No. *44054*

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92).

1st Longl.
 Transverse No. *2175* Depth "d" ✓
 Framing: Table No. ✓ Description *Angle frames, as approved*
 Longitudinal No. *6000*
 Proportions $\frac{\text{Length}}{\text{Depth}} =$ ✓
~~Deck~~ Sheerstrake *as approved*

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed

✱ *100 A.1 (Steel) Steam Trawler*
1 Dk
BK 7½", 4 BH, Lem, Lloyd's A+C.P.
Q. 83', F. 24'



Handwritten scribbles and initials at the top of the page.

Handwritten notes in the middle section, including "1000" and "1000".

Vertical handwritten text on the right side of the page.

Vertical handwritten text on the far right side.



© 2020 Lloyd's Register Foundation

33