

COPY

LLOYD'S REGISTER OF SHIPPING



Port..... HONG KONG.

Date..... 8th November, 1962.

This is to Certify *that I have*

surveyed the S.S. "NINA", 1463 *Gross tons, of Panama,*
whilst lying afloat at Hong Kong, on account of damage stated
caused whilst loading log cargo at Sejinkat, on the 12th
October, 1962,

and that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a report, stating that all/ temporary repairs recommended by
me have been completed to my satisfaction, also that I am
recommending that she be retained as now classed in the
Register Book without fresh record, subject to damaged frame
and shell plating in way of No.3 starboard hold (cement box)
being specially examined and dealt with as necessary at the
vessel's next dry docking, and to all conditions as previously
recommended.



D.C. Wood.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."

Cert. B 80m,4,62 (MADE AND PRINTED IN ENGLAND.)

© 2021

Lloyd's Register
Foundation

003838-003845-0321