

ELLENOR

78890

MON. SEP. 4 1922

(Received at London Office)

No. 21888

REPORT of SURVEY for REPAIRS, &c.

Writing Report Aug 3 1922 When handed in at Local Office Aug 3 1922 Port of New York

Survey held at Hoboken N.J. Date, First Survey 21 July Last Survey 25 July 1922

3 on the Wood, Iron or Steel S. "ELLENOR" EX MASON-CITY. Master

Built at Wilmington Del By whom Bethlehem Sp Corp When 1920 -

Owners U.S. Board Port belonging to Wilmington Del

Owners' Address See F.E.

Kept afloat or in Dry Dock? yes Name of Dock Destined Voyage

Capacity: Cell DBorDBa feet; uE&B feet; f feet; capacity tons. FPT tons; APT tons; MT feet tons.

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

General Observations, Opinion as to Class, Recommendation, &c.:— This vessel is eligible in my opinion to remain as classed, without record of survey.

Was a damage report made by anyone else? If so, by whom?

Alterations to Deck Tank. Deck Tank now dispensed with in this vessel centre line bulkhead cut, and one hatch 10'-0" x 17'-0" of plates and angles now fitted. Coaming plate 18" above deck .50 thick. 10 hatch covers fitted (wooden).

STATE OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items:—																																
Renewed																																								
Removed and Faired or Repaired																																								
Faired or Repaired in place																																								
PRESENT CONDITION OF THE	Stringers	Inner Bottom Plating	State if Tanks have been examined inside	State if Tanks now tested	Bulkheads	Ceiling	Cement or Asphalt (State which.)	Rudder	Steering gear and its connections	Windlass	Have Pumps now been examined and found efficient?	Have Sluice Valves now been examined and found efficient?	Have Watertight Doors now been examined and found efficient?	Dblg. Plates under Sounding Pipes	Engine Room Skylights	Coal Bunkers, Open'gs, Lids, &c.	Scuppers	Cargo Hatchways	Hatches	Planking of Wood Vessels	Caulking	Treenails	Breasthooks & Stemson	Transoms, Pointers, & Crutches ditto	Timbers of Frame at openings ditto	Ditto ditto at other places ditto	Stringers, Clamps & Shelves	Salting (State if examined.)	Copper, or Y.M. of Wood Vessels (State if on Felt.) When put on, Month Year	Boats	Masts, Yards, &c.	Condition, how ascertained (State if wedges removed)	Sails	Equipment letter	Anchors, No. of	Cables (State if now ranged)	length (on board) size	Rule length size	Hawser & Warps	Standing & Running Rigging

General Observations, Opinion as to Class, Recommendation, &c.:— This vessel is eligible in my opinion to remain as classed, without record of survey.

Fees applied for, Received by me, Surveyor to Lloyd's Register of Shipping.

Committee's Minute Character Assigned See Nms Rpt 3610



003971-003979-0027

Is Certificate required? If so, to be sent to