

Spacing of Solid floors .....  
**CENTRE GIRDER**, in Dbl. bottom, dpth. & thicknss. *34 1/2 x 38 - 36* *13 1/2 x 38 - 36* .....  
 Intercostal Plate, for ..... length .....

004624 004036-0082

3m 224

NOW CRAIGAVAD

1

Sent to Chief Surveyors ..... Received from Chief Surveyors .....

VESSEL'S NAME *Steel S<sub>c</sub> S<sub>k</sub> SAINT KENNETH* Report *Gls* No. *H3597*

**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report 24/5/02.)

Nature of Survey *1<sup>st</sup> Entry* When due .....

This vessel has been built in accordance with the Revised Rules and the owner's consent thereto has been obtained.

† 100 A.1. (Steel)

1 SK (rtl) "well SK"

Cell D.B. f 110' 1745, F.P.T 48t A.P.T. 16t.

B.K 7", 3 B.H, Cem, Lloyd's A CP.

QD 105', B 10', F 29'. "machy aft"



The Certificate of Classification, to be endorsed "Cargo battens not fitted." and the same notation to be entered in the Register Book.

Spacing .....	Beams, Forecastle Deck, Angle, Bulb Angle, Plate Tee Bulb or Channel	Tie Plates .....	Deck. Material and thickness <i>Wood</i>
---------------	--	------------------	--