

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

VESSEL'S NAME "SOMMELSDYK". Rpt. Cpn. No. 11015.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Long. No. 18833

Depth "d" -

2nd Long. No. 47662

Proportions = $\frac{L}{D}$ 11.48

Framing Bulb angle framing as approved. Sheerstrake As approved.

Full scantling vessel.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100A1 "Carrying vegetable oil in deep tanks"; "Carrying latex in tanks above FPT"

3 Dks

Cell DB 349' 1465t, DTsa 50', 1535t, DTsa 50' 2305t, tanks in way of tunnels 802t, Tanks above FPT 209t, FPT 97, APT 166t.

FK, 8BH, Lloyd's A & CP.

B 80' F 48'

O.L: 492.6



f.c.D. 13.10.39



© 2020

Lloyd's Register
Foundation