

Ship's Name SS/MS **M.V. 'POLURRIAN'.** Gross tons **339.**

Is there a rpt. 9? **YES. A & B.** Port **RABAU** Rpt. No. **2A5905**

No. of visits **TWO** First date **14-2-1963** Last date **16-2-1963.**

Interim Cert. issued & copy herewith? **YES** Damage rpt. issued & copy herewith? **NO.** Last rpt. (H.Q. only)

Date of completing rpt. **11-4-1963** Surveyed at, if different from Port above **---**

Surveyed afloat and/or in D.D. **SLIPWAY.** Last date of examination in D.D. **16-2-1963**

Has a Load Line Survey been held? **SEE ADDITIONAL REPORT** Freeboard Marks verified **SEE ADDITIONAL REPORT '8'.**

State which additional Rpt. 8 is attached: (Cont): (PS): (DR): (EQ): (Bg)

LOAD LINE SURVEY.

Survey fees **15 guineas.** Damage fee Expenses

S.A. fee

I have surveyed the above ship in accordance with the Rules for **DOCKING.**

The items now surveyed are detailed on this report. All were found or placed in good condition unless otherwise stated.

SHELL PLATING ; STERN FRAME AND RUDDER.

I recommend that this ship remain as classed with/without fresh record of dry docking

WITHOUT FRESH RECORD.



(Where conditions of class are recommended to be retained, imposed, amended or deleted, particulars must be stated above and on the interim certificate) **Surveyor Appt: by Lloyd's Agent** ✓

Chas. A. Sinclair
Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

ALSO FOR

SPL FOR

TRO

POSTING

HEADER

CERT



Lloyd's Register
Foundation

0400-0079-0013

25 APR 1963