


REPORT ON ANNUAL LOAD LINE SURVEY.

Name of Ship S.S. "QUEEN MAUD" Official Number 168743 Port of Registry Glasgow

Place of Survey Philadelphia, Pa. Dates of Survey 19 & 21 July, 1954 Date of last Load Line Survey 10th Sept., 1953

PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard deck.			
Coamings, their stays and stiffeners... ..	Good ✓		
Beams ... ..	" ✓		
Fore and afters ... ..	-		
*Covers ... ..	Good except	11 wood hatch covers to renew.	21st July, 1954 ✓
*Tarpaulins ... .. (State number per hatchway)	Good (2) ✓		
*Cleats and battens ... ..	"		
Lashings and their fittings ... ..	"		
Wedges ... .. (Is supply, including spares, adequate ?)	" - yes ✓		
2. Exposed on superstructure decks, including raised quarter decks. (on fo'castle)			
Coamings, <del>their stays and stiffeners</del> ... ..	Good ✓		
Beams ... ..	-		
Fore and afters ... ..	-		
*Covers ... ..	Steel - good ✓		
*Tarpaulins ... .. (State number per hatchway)	-		
*Cleats and battens ... ..	-		
Lashings and their fittings ... ..	-		
Wedges ... .. (Is supply, including spares, adequate ?)	-		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings ... ..	-		
Beams ... ..	-		
Fore and afters ... ..	-		
Covers ... ..	-		
Tarpaulins ... .. (State number per hatchway)	-		
Cleats and Battens ... ..	-		
Wedges ... .. (Is supply, including spares, adequate ?)	-		



© 2021  
Lloyd's Register


\*Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).





Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections ... ..	Good		
Closing arrangements ... ..	"		
5. To spaces below decks of superstructures which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections ... ..	-		
Closing arrangements ... ..	-		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements ... ..	Good		
7. Within partially enclosed superstructures.			
Closing arrangements ... ..	-		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings ... ..	Good		
Skylights, their fastenings, covers and lashings ... ..	"		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings ... ..	Good		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings ... ..	-		
11. Within partially enclosed superstructures.			
Doors and fastenings ... ..	-		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	-		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings, covers ... ..	Good		

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPERSTRUCTURE BULKHEADS.			
Forecastle ... ..	Portable steel plate - ✓ good		
Bridge, fore end... ..	-		
Bridge, after end ... ..	-		
Poop ... ..	-		
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures ... ..	-		
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves ... ..	Good ✓		
17. SIDE SCUTTLES AND DEADLIGHTS ... ..			
	Good ✓		
18. GUARD RAILS ... ..	Good except ✓	One guard rail to repair	21st July, 1954 ✓
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways ... ..	-		
20. LIFELINES (fittings and material) ... ..			
	Good. ?		
21. FREEING PORTS			
Shutters ... ..	-		
Protection bars ... ..	Fitted amidship only - ✓ good		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances ... ..	-		
23. ITEMS NOT INCLUDED IN THE FOREGOING			
	-		
24. LOAD LINE MARKS ... ..			
	Clearly marked ✓		



© 2021  
Lloyd's Register  
Foundation





Particulars of any change from the conditions given on the Load Line Certificate or on Form C 11.

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. †	Signature of Surveyor.	Place.	Date.
All	<i>L. J. Archibald</i> <i>per Mr. Mc</i>	Philadelphia, Pa.	21st July, 1954

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows :—

Signature of Surveyor

*L. J. Archibald*  
*per Mr. Mc*

Place

Philadelphia, Pa.

Date

21st July, 1954

Signature

*L. J. Archibald*  
*per Mr. Mc*

Date

21st July, 1954

† Insert "all" in case of a complete survey.

16 SEP 1954

Fee \$100.00

Exps. 4.00

Number of Visits two

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register  
Foundation