

Condition of Class

NAME OF VESSEL... DUNERA

Extract from Freeboard verification of marking form received
from the... GLASGOW Surveyors dated the... 11.8.37

Moulded depth	35	ft.	0	ins.
Corresponding draught	23	ft.	4	ins.
Moulded depth as shewn on draught sheet	35	ft.	$0\frac{1}{2}$	ins.
Tropical freeboard	11	ft.	$10\frac{1}{2}$	ins.
Summer "	11	ft.	$10\frac{1}{2}$	ins.
Winter "	11	ft.	$10\frac{1}{2}$	ins.
W.N.A. "	-	ft.	-	ins.
Fresh Water allowance	$5\frac{3}{4}$	ins.		

Marked from ~~wood~~/steel upper deck.

Checked by... *Jm*

Date... 11-2 SEP 1937



© 2021

Lloyd's Register
Foundation

004426-004431-0102