

1

Sent to Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Steel S.S. "Mulbera"*

Received from Chief Surveyors \_\_\_\_\_

Report *Gls.*No. *42040***For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/92.)

Nature of Survey \_\_\_\_\_

When due \_\_\_\_\_

✦ 100 Al. Steel

2 Dks. (Steel U track S)

bell. D.B. 400' 1447t, Tanks between Lunnels. 96' 243t FPT 92t, APT 104t  
 FK. 9BH. pt Cem. Lloyd's A+C.P. P 50' B 175' F 44'.

004527-004533-0081



© 2020

*M*  
 Lloyd's Register  
 Foundation  
*RKM*  
 7.7.22