

156 324

COPY

LLOYD'S REGISTER OF SHIPPING



Port Liverpool

Date 21st March, 1961.

This is to Certify *that I have*

surveyed the t.s.s. "BRAEMAR CASTLE", 17029 tons gross of London as she
afloat in Brocklebank Dock on the 18th January, 1961, and subsequently
in connection with Alterations and Advancement of Special Survey,

that I am transmitting to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
have been completed to my satisfaction, also that I am
recommending that she be continued as classed without fresh record of
S.S. and with the notation of S.S. (with date) on completion, subject to
the conditions at present attached to the ship's class being dealt with
as previously recommended.

P.T.O.

Andrew A Orrock

Surveyor to Lloyd's Register.

A.A. Orrock.


KEY TO ABBREVIATIONS

AS	Annual Survey
BS	Biennial Survey
DS	Docking Survey
NS	Cargo Battens not fitted (No Sparring)

SS	Hull Special Survey
SS(Dr)	Hull Special Survey (Drilling)
SS(M)	Hull Special Survey (Modified)
SS(P)	Hull Special Survey (Progressive)

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



004564-004572-0253

004564-004572-0254

126384

COPY

LOYD'S REGISTER OF SHIPPING

Now Done for Advancement of Special Survey.

Examined Internally and found good:-

- Fore Peak Tank.
- No. 6 D.B. (F.W.) s.
- No. 7 D.B. (F.W.) p & s.
- No. 8 D.B. (F.W.) p & s.
- Lub. Oil Drain Tank p & s.
- D.B. Lub. Oil C/Dam p & s.
- D.B. C/Dam between Nos. 2/3 D.B. Tanks.

Port
Date

Examined under pressure and found good :-
No. 1 D.B.

Examined and found good :-

- Forepeak spaces.
- Nos. 1 & 2 Holds.
- Nos. 1 & 2 Lower and Main Tween Decks.
- Crew accommodation on "C" deck forward of No. 4 hold.
- Passenger and Crew Accommodation on "B", "A", Promenade and Boat Deck.
- Pumping arrangements outwith Machinery Space.

Now Examined and found efficient but not accepted for Special Survey, on Permanent Repairs to be effected.

- No. 6 D.B. (F.W.) p.
- No. 2 D.B. (F.W.) p & s.

I am transmitting to the Committee of Lloyd's Register of Shipping, London, a Report, stating that all repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be continued on class without further survey and with the retention of S.S. (etc. date) on condition, subject to conditions at present attached to the ship's class being done to the satisfaction of the Committee.

Charles B. Lloyd

Surveyor to Lloyd's Register,
L.L. Lloyd.

KEY TO ABBREVIATIONS

AS	Annual Survey
HS	Hull Special Survey (Shell)
DS	Docking Survey (Moulded)
NS	Naval Special Survey (Progressive)



© 2021
Lloyd's Register
Foundation



...ertificate
...the C
...d that n
...y in any
... error o
...society."