

REPORT ON ANNUAL LOAD LINE SURVEY

Name of Ship... S.S. "BRAEMAR CASTLE"..... Official Number... 184728..... Port of Registry... L O N D O N

Place of Survey... L O N D O N Dates of Survey... 23rd & 27th January, 1959..... Date of last Load Line Survey... 13/12/57.....

PARTICULARS OF SURVEY

22. 31.10.61

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
HATCHWAYS, INCLUDING SMALL HATCHWAYS.			
1. Exposed on freeboard decks.			
Coaming, their stays and stiffeners			
Beams			
Fore and afters			
*Covers			
*Tarpaulins			
(State number per hatchway)			
*Cleats and battens			
Lashings and their fittings			
Wedges			
(Is supply, including spares, adequate?)			
2. Exposed on superstructure decks, including raised quarter decks.			
Coamings, their stays and stiffeners	Good. ✓		
Beams	" ✓		
Fore and afters	- ✓		
*Covers	Good except {	No.1 Hatchway: 4 covers to renew.	27/1/59.
*Tarpaulins	" {	No.2 " : 3 " " "	
(State number per hatchway) 3.			
*Cleats and battens	" ✓		
Lashings and their fittings ... Locking bars. ✓	" ✓		
Wedges	" ✓		
(Is supply, including spares, adequate?)	Yes. ✓		
3. Within superstructures not intact or not protected by Class I closing appliances.			
Coamings			
Beams			
Fore and afters			
Covers			
Tarpaulins			
(State number per hatchway)			
Cleats and battens			
Wedges			
(Is supply, including spares, adequate?)			
VENTILATORS IN EXPOSED POSITIONS.			
4. To spaces below freeboard deck.			
Coamings, their supports and deck connections	Good. ✓		
Closing arrangements	" ✓		
5. To spaces below decks of superstructure which are intact or closed by Class I appliances.			
Coamings, their supports and deck connections	Good. ✓		
Closing arrangements	" ✓		
AIR PIPES.			
6. Exposed on freeboard and superstructure decks.			
Closing arrangements	Good. ✓		
7. Within superstructures not intact or not protected by Class I closing appliances.			
Closing arrangements	- ✓		
MACHINERY CASINGS.			
8. Casing Top.			
Fiddley openings, their covers and fastenings	- ✓		
Skylights, their fastenings, covers and lashings	Good. ✓		
9. Exposed on freeboard and raised quarter decks.			
Doors and fastenings	- ✓		
10. Exposed on superstructure decks other than raised quarter decks.			
Doors and fastenings	- ✓		
11. Within superstructures not intact or not protected by Class I closing appliances.			
Doors and fastenings	- ✓		
12. FLUSH BUNKER SCUTTLES and chain attachments			
	- ✓		
13. COMPANIONWAYS, including deckhouses enclosing ladderways.			
Doors, fastenings covers,	Good. ✓		

* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Ministry of Transport Circular 1687, paragraph 117 (i)).

Items examined.	Condition in which found.	Repairs.	
		Necessary.	Date effected.
14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.			
Forecastle	Good. ✓		
Bridge, fore end			
Bridge, after end			
Poop			
15. GANGWAY, CARGO AND COALING PORTS.			
In ship's side and superstructures	Good except Shell door, upper, port side to re-rubber.		27/1/59.
16. SCUPPERS AND SANITARY DISCHARGE PIPES.			
Valves	Good. ✓	{ Galley shoot, Starb'd. to re-rubber. E.R. shoot, Port to re-rubber. }	27/1/59.
17. SIDE SCUTTLES AND DEADLIGHTS	Good. ✓		
18. GUARD RAILS	Good. ✓		
19. PROTECTION AND ACCESS TO CREW'S QUARTERS.			
Gangways	- ✓		
20. LIFELINES (fittings and material)	- ✓		
21. FREEING PORTS.			
Shutters	Open rails. ✓		
Protection bars	✓		
22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.			
Fittings or appliances	-		
23. ITEMS NOT INCLUDED IN THE FOREGOING.			
	-		
24. LOAD LINE MARKS	Verified. ✓		

Certificate A. To be signed by Surveyor in respect of a partial or complete survey.

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Ministry of Transport Circular 1687, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
All.	<i>R. A. Jeffery.</i> R. A. JEFFERY.	L O N D O N .	23rd January, 1959.

Certificate B. To be signed by Surveyor completing the survey.

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters have been maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the position of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor *R. A. Jeffery.* Place L O N D O N . Date 27/1/59.

Signature *R. A. Jeffery.*

Date 29th January, 1959.


Fee £25..0..0d.

Expenses 7/-

Number of Visits 2.

Particulars of any change from the conditions given on the Load Line Certificate or on Form C11 should be reported on Form C11 (contd.) and attached to the Form C11 on the Ship, a copy being forwarded to the Freeboard Department.

Surveyors should note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on a certified copy of the certificate unless the original certificate has been produced to and endorsed by the Surveyor.



© 2021

Lloyd's Register
Foundation