

umps worked from the Main Engines. No. 2 Diameter 2 3/4" 15"

s/s "Homewood"

Gls 46270

It is submitted that the Glasgow Surveyors
requested to state the number & diameter of
the bilge section pipes in the hold & engine
space & omitted from their report.

h. 7/7/27

See Gls LK 5/8/27

J. P.

J. W. D.

26/1/27

004769-004777-0183

umps in connection with the machinery and all boiler mountings accessible at all times

yes.