

F.E.

by Chief Ship Surveyor

Received from Chief Ship Surveyor

EL'S NAME *Stl T.S.M/V BRITANNIC* Rpt. *Bel* No. *10409*

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

1st Lang
 Transverse No. *35951* Depth "d" *✓*
 Framing: Table No. *✓* Description *Channel frames with reverse frames as approved*
 Longitudinal No. *91711*
 Proportions $\frac{\text{Length}}{\text{Depth}} =$
 Deck Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the rules and the approved plans, and it is submitted she is eligible to be classed *✠ 1.00 A. 1 (Steel)* "with freeboard," as recommended. *Carrying Vegetable oil in after deep tanks forward.* The Summer freeboard of *19-2* from centre of disc to top of statutory deck line at *✓* deck, now marked on the vessel's sides, to be inserted in the classification certificate, and recorded in the Register Book, and further, the remaining freeboards, shown on the accompanying verification form to be inserted in the certificate of classification.



D^W (Stl - Weather D^W WS) 5th D^W (Stl) in holds except aftermost hold, 6th D^W (Stl) in Nos 1-2 & 3 holds
all D.B. 582' 3230t, D.T.s 56' 1756t, F.P.T. 181t, A.P.T. 2231t.
K + BK 2 1/2", 12 B.H., Cem, Holds A VCP.
325' F 110'
upper Bridge 118'

The Surveyor should be requested to state whether the notation "Carrying vegetable oil in after deep tank forward" is desired by the owner.

Solid Floors, thickness and spacing	<i>52</i>	<i>32</i>	<i>✓</i>
-------------------------------------	-----------	-----------	----------