

S/R.

119.

F.E.

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME Steel S.S. "WHIN" Rpt. Hub. No. 32246

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Transverse No. 37 Depth "d" 10.5'
 Framing: Table No. 3 Description Bulb angle as approved.
 Longitudinal No. 5624
 Proportions $\frac{\text{Length}}{\text{Depth}} =$ 12.66

Upper Deck Sheerstrake as approved.

This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed 100 A.1. (steel) as recommended.

1 Dk (steel) "Well Dk."

FPT 48t. APT 21t.

FK. 3BH. Com. Lloyd's A.Y.C.P. a 86', B 9', F 25'

Machy. Aft.

5624
 74 x 7 x $\frac{3}{8}$ 179
 86 x 3 301
 5104

M

AES
6-11-20



© 2020 Lloyd's Register Foundation