

4E

12 NOV 1957

per Surveyor.....

Received from Chief Engineer Surveyor.....

BALLYDENE

Bel

16392

REPORT

No.

Docking. Screwshaft seen.

MBS due 10.57, now held.

Steampipes examined.

IT IS SUBMITTED this vessel is eligible for the
record TS (CL) 10.57, MBS 10.57, and SPS 10.57.

It is concluded that the boiler mountings, doors
and fastenings were examined, but the Surveyor should be
asked to confirm this.

yes, see
Bel. 18.11.57
JL



9.8.2021
8.11.57.

Lloyd's Register
Foundation

005038-005046-0013