

s/s. "Carnegie."

Nwc. 80400

It is submitted, before this case receives consideration, the Newcastle Surveyors should be requested to state whether the screw shaft is fitted with a continuous liner, two liners or three liners & if the latter whether an oil gland is fitted at the after end of the stern bush.

29/5/26
See Nwc. 80400
29/5/26



© 2021

JAG

27/5/26

Lloyd's Register
Foundation

005038-005046-0091

s/c Glen



© 2021

Lloyd's Register
Foundation