

Port of Newcastle upon Tyne  
3<sup>rd</sup> July 1952

REPORT ON MASTS, SPARS, AND RIGGING.

Dear Sirs

Having, in accordance with your instructions,  
examined the Masts, Spars, Iron Work of same, and Rigging, of the  
of Vessel V SAN CASTO, Lying at "The Middle Dock, E. Eng. Co. Ltd."  
(Date of examination) 10<sup>th</sup> March 1952


I have to report that I found the Ironwork of Foremast in  
good condition, but the following fittings found  
to be corroded and worn, namely, the lower section  
of Foremast Ladder, and 2 in number Topmast  
and Steps, also 2 in number support brackets for  
escape Pipe, recommend these for renewal,  
the following Standing Rigging found to be  
in poor condition, recommend same for renewal  
namely 4 in number Foremast Shrouds,  
remainder of Rigging in good condition, but recommend  
ungarn service and bearings be repaired as found necessary.

Yours Faithfully A. F. Clevery

£ 1 : 0 : 0<sup>d</sup>

The Surveyors,  
Lloyd's Register of Shipping,

NEWCASTLE-ON-TYNE



© 2020

Lloyd's Register  
Foundation

005321-005324-0063