

1

D.L. 122

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME

Steel S. S. Drake

Report

No

No. 41735


For the CHIEF SHIP SURVEYOR ~~and CHIEF ENGINEER SURVEYOR.~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report 24/5/02.)

Nature of Survey

When due

✱ 100-A-1. (Steel) Shelter Deck with preboard.
 1st Dk (Steel) ✓ Shelter Dk (Steel) 2nd Dk (Steel) in N° 2 hold
 All Dk 215' 339t FPT 16t, APT 24t,
 FK, 5BH to Shelter Dk, Curr. Plyds A. CP, 1363' in Shelter Dk.



© 2021

Lloyd's Register
Foundation

005358-005366-0106

[Signature]
 23-2-22