

Fld. 1872.

26 OCT 1942  
33803

# Lloyd's Register of Shipping.

## REPORT ON ANNUAL LOAD LINE SURVEY.

Ship "Empire Star" Official Number 162474 Port of Registry London.  
Survey Hull Dates of Survey 15<sup>th</sup> 16<sup>th</sup> + 21/10/42 Date of last Load Line Survey 8/12/41

### PARTICULARS OF SURVEY.

Items examined.	Condition in which found.	Repairs.			
		Necessary.	Date effected.		
<b>HATCHWAYS, INCLUDING SMALL HATCHWAYS.</b>					
<b>1. Exposed on freeboard deck.</b>					
Coamings, their stays and stiffeners	Satisfactory	<i>The following repairs &amp; renewals have effected:- A total of 10 wood latches renewed. 6 tarpaulins " Locking bars &amp; cleats on festle store hatches renewed. Locking bars fitted to each section of No 1 Hatch. Hinged steel plates &amp; clips fitted at bridge front bulkhead now replaced by bolted steel plates.</i>	21/10/42		
Beams	Satisfactory				
Fore and afters	"				
*Covers	" (3)				
*Tarpaulins (State number per hatchway)	"				
Battens and battens	" Adequate spares.				
Lashings and their fittings	"				
Wedges (Is supply, including spares, adequate?)	" Adequate spares.				
<b>2. Exposed on superstructure decks, including raised quarter decks.</b>					
Coamings, their stays and stiffeners	Satisfactory				
Beams	"				
Fore and afters	"				
*Covers	Satisfactory				
*Tarpaulins (State number per hatchway)	" (2)				
*Cleats and battens	"				
Lashings and their fittings	"				
Wedges (Is supply, including spares, adequate?)	" Adequate spares.				
<b>3. Within superstructures not intact or not protected by Class I closing appliances.</b>					
Coamings	Satisfactory				
Beams	"				
Fore and afters	"				
Covers	Satisfactory				
Tarpaulins (State number per hatchway)	" (2)				
Cleats and Battens	Satisfactory				
Wedges (Is supply, including spares, adequate?)	" Adequate spares.				
<b>EXPOSED POSITIONS.</b>					
<b>NOTICE SE freeboard deck.</b>					
Stays and deck connections	Satisfactory				
Structure which are intact or not	"				
Deck connections	Satisfactory				
Closing arrangements	"				
<b>AIR PIPES.</b>					
<b>6. Exposed on freeboard and superstructure decks.</b>					
Closing arrangements	Satisfactory				
<b>7. Within partially enclosed superstructures.</b>					
Closing arrangements	✓				
<b>MACHINERY CASINGS.</b>					
<b>8. Casing Top.</b>					
Fiddle openings, their covers and fastenings	Satisfactory				
Skylights, their fastenings, covers and lashings	"				
<b>9. Exposed on freeboard and raised quarter decks.</b>					
Doors and fastenings	"				
<b>10. Exposed on superstructure decks other than raised quarter decks.</b>					
Doors and fastenings	"				
<b>Within partially enclosed superstructures.</b>					
Doors and fastenings	"				
<b>FLUSH BUNKER SCUTTLES and chain attachments</b>					
	None.				
<b>11. COMPANIONWAYS, including deckhouses enclosing ladderways.</b>					
Doors, fastenings, covers	Satisfactory				

The following repairs & renewals  
have effected:-  
A total of 6 wood latches renewed.  
6 tarpaulins " "  
Locking bars & cleats on fiddle  
store hatches renewed.  
Locking bar fitted to each section  
of No 1 Hatch.  
Hinged steel plates & clips fitted  
at bridge front bulkhead now  
replaced by bolted steel plates.

21/10/42.

005387-005396-0230

\* Tarpaulins, battens, covers, etc., to be examined in place as well as separately (see Board of Trade Circular 1687, paragraph 117 (i)).



© 2020

Lloyd's Register  
Foundation



Items examined.	Condition in which found.	Repairs.	Necessary.	Date.
<b>14. CLOSING APPLIANCES FOR OPENINGS IN SUPER-STRUCTURE BULKHEADS.</b>				
Forecastle ...	Satisfactory			
Bridge, fore end ...	"			
Bridge, after end ...	"			
Poop ...	"			
<b>15. GANGWAY, CARGO AND COALING PORTS.</b>				
In ship's side and superstructures	Satisfactory			
<b>16. SCUPPERS AND SANITARY DISCHARGE PIPES.</b>				
Valves ...	"			
<b>17. SIDE SCUTTLES AND DEADLIGHTS</b>				
	"			
<b>18. GUARD RAILS</b>				
	"			
<b>19. PROTECTION AND ACCESS TO CREW'S QUARTERS.</b>				
Gangways ...	"			
<b>20. LIFELINES (fittings and material)</b>				
	"			
<b>21. FREEING PORTS.</b>				
Shutters ...	"			
Protection bars ...	"			
<b>22. TIMBER, TANKER OR SPECIAL STEAMER LOAD LINES.</b>				
Fittings or appliances	✓			
<b>23. ITEMS NOT INCLUDED IN THE FOREGOING.</b>				
	✓			
<b>24. LOAD LINE MARKS</b>				
	Correct.			

**Certificate A. To be signed by Surveyor in respect of a partial or complete survey.**

I have surveyed the ship named at the head hereof, to the extent indicated below, in accordance with the instructions contained in Board of Trade regulations, and the requisite details of the survey have been entered herein.

Index Nos. of items examined. († Insert "all" in case of a complete survey.)	Signature of Surveyor.	Place.	Date.
All.	<i>W.B. Edwards</i>	Hull	21/10/1942

**Certificate B. To be signed by Surveyor completing the survey.**

I am satisfied

- (i) that the fittings and appliances for the protection of openings, the guard rails, the freeing ports and the means of access to the crew's quarters are maintained on the ship in as effective a condition as they were in when the certificate was issued; and
- (ii) that no material alterations have taken place in the hull or superstructures of the ship which affect the positions of the load lines.

I have endorsed the Load Line Certificate and the certified copy as follows:—

Signature of Surveyor	Place	Date
<i>W.B. Edwards</i>	Hull	21/10/1942

Number of Visits *7*

Particulars of any change from the conditions given on the Load Line Certificate or on Form C11 should be reported on Form C11 (contd.) and a copy being forwarded to the Freeboard Department.

of the certificate note that there is only one valid certificate, and the above endorsement should be made thereon. No entry should be made on the Ship, a copy being forwarded to the Freeboard Department.