

ed by Chief Ship Surveyor

Received from Chief Ship Surveyor

SHIP'S NAME Steel S.S. "SAN FELIX". Rpt. Nwco. No. 74521

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee. "Letter 9.8.21.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

re of Survey

From a letter received from the Newcastle Surveyors it would appear that the forecastle deck beams and beam knees are not in accordance with the approved plan.

The Surveyors should be requested to forward the approved plan of the forecastle together with a sketch showing the compensation proposed to be fitted in this ~~deck~~ and the sister vessel No. 913 now building.

Lr. Nwco. 20/8/21



© 2020

Lloyd's Register
Foundation

20. 8. 21.

005387-005396-0313